

IN THE UNITED STATES PATENT & TRADEMARK OFFICE

IN RE APPLICATION OF: U.S. Patent No. 7,715,464

USPTO CONFIRMATION CODE: 2864

APPLICATION NO.: 10/595,115

PCT FILED: July 10, 2004

U.S. FILED: August 16, 2006

EXAMINER: David C. Payne

GROUP ART UNIT: 2611

FOR: POSITIONING OF A PATH SEARCHER WINDOW IN A CDMA RECEIVER

37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION
FOR APPLICANT MISTAKE

HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

SIR:

The following is a request for a certificate of correction in Serial Number 10/595,115 now Patent Number 7,715,464.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

The errors were the fault of the applicant, accordingly, please charge \$100.00 to our Deposit Account No. 50-1379. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The exact locations where the errors appear in the patent and patent application are as follows:

$$\tau = \frac{\sum_{d \in \Omega_d} \tau_d(S_d - Z)}{\sum_{d \in \Omega_d} \tau_d(S_d - Z)}.$$

In Column 11, Lines 17-20, delete “ ” and

$$\tau = \frac{\sum_{d \in \Omega'_d} \tau_d(S_d - Z)}{\sum_{d \in \Omega'_d} \tau_d(S_d - Z)}.$$

insert -- --, therefor.

(ORIGINALLY FILED SPECIFICATION DATED FEBRUARY 21, 2006,
PAGE 19, LINES 3-4)

The requested corrections are attached on Form PTO 1050.

Respectfully Submitted

, 2010

DATE

/SIDNEY L. WEATHERFORD, Reg#45602/

Sidney L. Weatherford
Registration No. 45602
Attorney of Record